



International Telecommunication Union  
Radiocommunication Bureau

BR IFIC No / Date  
BR IFIC No / Date  
BR IFIC No / Fecha

2933 / 10.11.2020

Section Spéciale No  
Special Section No  
Sección Especial No

GE75/189

Date limite pour la réception des commentaires :

Expiry date for the receipt of comments :

Fecha límite para la recepción de los comentarios :

02.03.2021

	En-têtes des colonnes	Columns headings	Títulos de las columnas
AMS	PLN (Plan) ADD(Addition) MOD(modification) SUP(Suppression)	PLN (Plan) ADD(Addition) MOD(modification) SUP(Suppression)	PLN (Plan) ADD(Adición) MOD(modificación) SUP(Anulación)
Id No	Numéro d'identification du BR	BR identification number	Número de identificación de la BR
JN	Opération : HJ(jour), HN(Nuit)	Operation : HJ (Day-time), HN(Night-time)	Operación : HJ (día) o HN (noche)
Freq	Fréquence assignée, kHz	Assigned frequency, kHz	Frecuencia asignada, kHz
Sync	S pour réseau synchronisé	S for a synchronized network	S para una red sincronizada
Site name	Nom de l'emplacement d'émission	Name of the transmitter site	Nombre del emplazamiento de transmisión
Ctry	Symbole de pays ou zone géographique	Country or geographical zone symbol	Símbolo del país o zona geográfica
Geocoords	Coordonnées géographiques	Geographical coordinates	Coordenadas geográficas
Pr	Rapport de protection canal adjacent	Adjacent channel protection ratio	Relación de protección en canal adyacente
Bdw	Largeur de bande, kHz	Bandwidth, kHz	Anchura de banda, kHz
Power	Puissance de l'onde porteuse, kW	Carrier power, kW	Potencia de la portadora, kW
Emrp	Rayonnement maximal, dB(kW)	Maximum radiation, dB(kW)	Radiación máxima, dB(kW)
Azm	Azimut de rayonnement maximal	Azimuth of maximum radiation	Acimut de radiación máxima
Ant	Type d'antenne, A ou B	Antenna type, A or B	Tipo de antena, A o B
Hgt	Hauteur de l'antenne, m	Height of antenna, m	Altura de la antena, m
Cond	Conductivité du sol, mS/m	Ground conductivity, mS/m	Conductividad del suelo, mS/m
Rmks	Commentaires du BR	Comments of the BR	Comentarios de la BR
Coord A	Coordination effectuée	Coordination effected	Coordinación efectuada
Coord B	Coordination nécessaire	Coordination required	Coordinación a efectuar

## Partie / Part / Parte A

AMS	Id No	JN	Freq	Sync	Site name	Ctry	Geocoords	Pr	Bdw	Power	Emrp	Azm	Ant	Hgt	Cond	Rmks	Coord_A	Coord_B
ADD	120234552	HJ	621		Kediri-1	INS	112E09 07S45	9	18	0.5	-3.0		A	121	10			
ADD	120234552	HN	621		Kediri-1	INS	112E09 07S45	9	18	0.5	-3.0		A	121	10			
ADD	120234553	HJ	666		Bogor-2	INS	106E57 06S38	9	18	0.5	-3.0		A	113	10			
ADD	120234553	HN	666		Bogor-2	INS	106E57 06S38	9	18	0.5	-3.0		A	113	10			
ADD	120234554	HJ	684		Depok-1	INS	106E47 06S22	9	18	0.5	-3.0		A	110	10			
ADD	120234554	HN	684		Depok-1	INS	106E47 06S22	9	18	0.5	-3.0		A	110	10			
ADD	120234555	HJ	702		Cirebon-2	INS	108E30 06S44	9	18	0.5	-3.0		A	107	10			
ADD	120234555	HN	702		Cirebon-2	INS	108E30 06S44	9	18	0.5	-3.0		A	107	10			
ADD	120234556	HJ	720		Cilacap-1	INS	108E45 07S18	9	18	0.5	-3.0		A	105	10			
ADD	120234556	HN	720		Cilacap-1	INS	108E45 07S18	9	18	0.5	-3.0		A	105	10			
ADD	120234557	HJ	720		Semarang-2	INS	110E24 07S00	9	18	0.5	-3.0		A	105	10			
ADD	120234557	HN	720		Semarang-2	INS	110E24 07S00	9	18	0.5	-3.0		A	105	10			
ADD	120234558	HJ	738		Tangerang-1	INS	106E36 06S21	9	18	0.5	-3.0		A	102	10			
ADD	120234558	HN	738		Tangerang-1	INS	106E36 06S21	9	18	0.5	-3.0		A	102	10			
ADD	120234559	HJ	774		Salatiga-1	INS	110E30 07S19	9	18	0.5	-3.0		A	97	10			
ADD	120234559	HN	774		Salatiga-1	INS	110E30 07S19	9	18	0.5	-3.0		A	97	10			
ADD	120234560	HJ	783		Banjarmasin-1	INS	114E37 03S19	9	18	0.5	-3.0		A	96	10			
ADD	120234560	HN	783		Banjarmasin-1	INS	114E37 03S19	9	18	0.5	-3.0		A	96	10			
ADD	120234561	HJ	792		Cilacap-2	INS	109E14 07S37	9	18	0.5	-3.0		A	95	10			
ADD	120234561	HN	792		Cilacap-2	INS	109E14 07S37	9	18	0.5	-3.0		A	95	10			
ADD	120234562	HJ	792		Jakarta-1	INS	106E58 06S13	9	18	0.5	-3.0		A	95	10			
ADD	120234562	HN	792		Jakarta-1	INS	106E58 06S13	9	18	0.5	-3.0		A	95	10			SNG
ADD	120234563	HJ	810		Majalengka-1	INS	108E13 06S50	9	18	0.5	-3.0		A	93	10			
ADD	120234563	HN	810		Majalengka-1	INS	108E13 06S50	9	18	0.5	-3.0		A	93	10			
PLN	075010201	HJ	1602		BIELLA	I	008E03 45N34	0	9	1	0.0		A	50	1			
PLN	075010201	HN	1602		BIELLA	I	008E03 45N34	0	9	1	0.0		A	50	1			
MOD	120238912	HJ	828		Corso Alberto Rivetti-BIELLA	I	008E04 45N33	0	9	3	4.8		A	50	1			
MOD	120238912	HN	828		Corso Alberto Rivetti-BIELLA	I	008E04 45N33	0	9	3	4.8		A	50	1			D
ADD	120234564	HJ	828		Makassar-1	INS	119E24 05S08	9	18	0.5	-3.0		A	91	10			
ADD	120234564	HN	828		Makassar-1	INS	119E24 05S08	9	18	0.5	-3.0		A	91	10			
ADD	120234565	HJ	828		Malang-2	INS	112E38 07S58	9	18	0.5	-3.0		A	91	10			
ADD	120234565	HN	828		Malang-2	INS	112E38 07S58	9	18	0.5	-3.0		A	91	10			
ADD	120234566	HJ	846		Surabaya-2	INS	112E45 07S13	9	18	0.5	-3.0		A	89	10			
ADD	120234566	HN	846		Surabaya-2	INS	112E45 07S13	9	18	0.5	-3.0		A	89	10			AUS
ADD	120234567	HJ	846		Surakarta-1	INS	110E49 07S33	9	18	0.5	-3.0		A	89	10			
ADD	120234567	HN	846		Surakarta-1	INS	110E49 07S33	9	18	0.5	-3.0		A	89	10			AUS

## Partie / Part / Parte A

AMS	Id No	JN	Freq	Sync	Site name	Ctry	Geocoords	Pr	Bdw	Power	Emrp	Azm	Ant	Hgt	Cond	Rmks	Coord_A	Coord_B
ADD	120234568	HJ	864		Surabaya-3	INS	112E44 07S14	9	18	0.5	-3.0		A	87	10			
ADD	120234568	HN	864		Surabaya-3	INS	112E44 07S14	9	18	0.5	-3.0		A	87	10			
ADD	120234569	HJ	882		Jakarta-2	INS	106E53 06S18	9	18	0.5	-3.0		A	86	10			
ADD	120234569	HN	882		Jakarta-2	INS	106E53 06S18	9	18	0.5	-3.0		A	86	10			
ADD	120234570	HJ	918		Bandung-2	INS	107E35 06S54	9	18	0.5	-3.0		A	82	10			
ADD	120234570	HN	918		Bandung-2	INS	107E35 06S54	9	18	0.5	-3.0		A	82	10			
ADD	120233671	HJ	927		PERUGIA	I	012E25 43N03	0	9	100	21.0		B			1		SVN
ADD	120233671	HN	927		PERUGIA	I	012E25 43N03	0	9	100	21.0		B			1		ALB; ALG; BEL; GRC; SVN; TUR
ADD	120234571	HJ	936		Buleleng-1	INS	115E04 08S06	9	18	0.5	-3.0		A	81	10			
ADD	120234571	HN	936		Buleleng-1	INS	115E04 08S06	9	18	0.5	-3.0		A	81	10			
ADD	120234572	HJ	936		Sukabumi-1	INS	107E00 07S00	9	18	0.5	-3.0		A	81	10			
ADD	120234572	HN	936		Sukabumi-1	INS	107E00 07S00	9	18	0.5	-3.0		A	81	10			
ADD	120234573	HJ	954		Gresik-1	INS	112E39 07S09	9	18	0.5	-3.0		A	79	10			
ADD	120234573	HN	954		Gresik-1	INS	112E39 07S09	9	18	0.5	-3.0		A	79	10			
ADD	120234574	HJ	990		Banjar-1	INS	114E52 03S24	9	18	0.5	-3.0		A	76	10			
ADD	120234574	HN	990		Banjar-1	INS	114E52 03S24	9	18	0.5	-3.0		A	76	10			
ADD	120234575	HJ	990		Gunungsitoli-1	INS	097E35 01N15	9	18	0.5	-3.0		A	76	10			
ADD	120234575	HN	990		Gunungsitoli-1	INS	097E35 01N15	9	18	0.5	-3.0		A	76	10			
ADD	120234576	HJ	1026		Kediri-1	INS	112E06 07S43	9	18	0.5	-3.0		A	74	10			
ADD	120234576	HN	1026		Kediri-1	INS	112E06 07S43	9	18	0.5	-3.0		A	74	10			AUS
ADD	120234578	HJ	1062		Semarang-3	INS	110E25 06S57	9	18	0.5	-3.0		A	71	10			
ADD	120234578	HN	1062		Semarang-3	INS	110E25 06S57	9	18	0.5	-3.0		A	71	10			
ADD	120234577	HJ	1062		Surabaya-4	INS	112E40 07S19	9	18	0.5	-3.0		A	71	10			
ADD	120234577	HN	1062		Surabaya-4	INS	112E40 07S19	9	18	0.5	-3.0		A	71	10			
ADD	120234579	HJ	1098		Jakarta-3	INS	106E47 06S10	9	18	0.5	-3.0		A	69	10			
ADD	120234579	HN	1098		Jakarta-3	INS	106E47 06S10	9	18	0.5	-3.0		A	69	10			
ADD	120234581	HJ	1116		Bandung-3	INS	107E43 06S56	9	18	0.5	-3.0		A	68	10			
ADD	120234581	HN	1116		Bandung-3	INS	107E43 06S56	9	18	0.5	-3.0		A	68	10			
ADD	120234580	HJ	1116		Jeneponto-1	INS	119E54 05S26	9	18	0.5	-3.0		A	68	10			
ADD	120234580	HN	1116		Jeneponto-1	INS	119E54 05S26	9	18	0.5	-3.0		A	68	10			
ADD	120234582	HJ	1134		Klaten-1	INS	110E37 07S47	9	18	0.5	-3.0		A	67	10			
ADD	120234582	HN	1134		Klaten-1	INS	110E37 07S47	9	18	0.5	-3.0		A	67	10			
ADD	120234583	HJ	1152		Bandung-4	INS	107E37 06S55	9	18	0.5	-3.0		A	66	10			
ADD	120234583	HN	1152		Bandung-4	INS	107E37 06S55	9	18	0.5	-3.0		A	66	10			
ADD	120234584	HJ	1152		Surabaya-5	INS	112E43 07S16	9	18	0.5	-3.0		A	66	10			
ADD	120234584	HN	1152		Surabaya-5	INS	112E43 07S16	9	18	0.5	-3.0		A	66	10			

## Partie / Part / Parte A

AMS	Id No	JN	Freq	Sync	Site name	Ctry	Geocoords	Pr	Bdw	Power	Emrp	Azm	Ant	Hgt	Cond	Rmks	Coord_A	Coord_B
ADD	120234585	HJ	1170		Bogor-3	INS	106E46 06S29	9	18	0.5	-3.0		A	65	10			
ADD	120234585	HN	1170		Bogor-3	INS	106E46 06S29	9	18	0.5	-3.0		A	65	10			
ADD	120234586	HJ	1170		Surabaya-6	INS	112E41 07S15	9	18	0.5	-3.0		A	65	10			
ADD	120234586	HN	1170		Surabaya-6	INS	112E41 07S15	9	18	0.5	-3.0		A	65	10			
ADD	120234587	HJ	1188		Surabaya-7	INS	112E43 07S12	9	18	0.5	-3.0		A	65	10			
ADD	120234587	HN	1188		Surabaya-7	INS	112E43 07S12	9	18	0.5	-3.0		A	65	10			AUS
ADD	120234588	HJ	1224		Banyuwangi-1	INS	114E07 08S21	9	18	0.5	-3.0		A	62	10			
ADD	120234588	HN	1224		Banyuwangi-1	INS	114E07 08S21	9	18	0.5	-3.0		A	62	10			
ADD	120234589	HJ	1242		Surabaya-8	INS	112E41 07S16	9	18	0.5	-3.0		A	61	10			
ADD	120234589	HN	1242		Surabaya-8	INS	112E41 07S16	9	18	0.5	-3.0		A	61	10			
ADD	120234590	HJ	1260		Pasuruan-1	INS	112E54 07S39	9	18	0.5	-3.0		A	60	10			
ADD	120234590	HN	1260		Pasuruan-1	INS	112E54 07S39	9	18	0.5	-3.0		A	60	10			AUS
ADD	120234591	HJ	1278		Surabaya-9	INS	112E45 07S16	9	18	0.5	-3.0		A	59	10			
ADD	120234591	HN	1278		Surabaya-9	INS	112E45 07S16	9	18	0.5	-3.0		A	59	10			
ADD	120234592	HJ	1314		Karangayar-1	INS	110E55 07S35	9	18	0.5	-3.0		A	58	10			
ADD	120234592	HN	1314		Karangayar-1	INS	110E55 07S35	9	18	0.5	-3.0		A	58	10			
ADD	120234593	HJ	1368		Karo-1	INS	098E30 03N11	9	18	0.5	-3.0		A	55	10			
ADD	120234593	HN	1368		Karo-1	INS	098E30 03N11	9	18	0.5	-3.0		A	55	10			
ADD	120234594	HJ	1368		Sumedang-1	INS	107E48 06S54	9	18	0.5	-3.0		A	55	10			
ADD	120234594	HN	1368		Sumedang-1	INS	107E48 06S54	9	18	0.5	-3.0		A	55	10			
ADD	120234595	HJ	1440		Kudus-1	INS	110E50 06S46	9	18	0.5	-3.0		A	53	10			
ADD	120234595	HN	1440		Kudus-1	INS	110E50 06S46	9	18	0.5	-3.0		A	53	10			
ADD	120234596	HJ	1458		Bandung-5	INS	107E35 06S52	9	18	0.5	-3.0		A	52	10			
ADD	120234596	HN	1458		Bandung-5	INS	107E35 06S52	9	18	0.5	-3.0		A	52	10			
ADD	120234597	HJ	1476		Bandung-6	INS	107E40 06S49	9	18	0.5	-3.0		A	51	10			
ADD	120234597	HN	1476		Bandung-6	INS	107E40 06S49	9	18	0.5	-3.0		A	51	10			
ADD	120234598	HJ	1476		Semarang-4	INS	110E26 07S00	9	18	0.5	-3.0		A	51	10			
ADD	120234598	HN	1476		Semarang-4	INS	110E26 07S00	9	18	0.5	-3.0		A	51	10			
ADD	120234599	HJ	1494		Blora-1	INS	111E34 07S09	9	18	0.5	-3.0		A	51	10			
ADD	120234599	HN	1494		Blora-1	INS	111E34 07S09	9	18	0.5	-3.0		A	51	10			
ADD	120234600	HJ	1512		Balikpapan-1	INS	116E49 01S15	9	18	0.5	-3.0		A	50	10			
ADD	120234600	HN	1512		Balikpapan-1	INS	116E49 01S15	9	18	0.5	-3.0		A	50	10			
ADD	120234601	HJ	1530		Jakarta-4	INS	106E50 06S11	9	18	0.5	-3.0		A	50	10			
ADD	120234601	HN	1530		Jakarta-4	INS	106E50 06S11	9	18	0.5	-3.0		A	50	10			



## Partie / Part / Parte B

<i>AMS</i>	<i>Id No</i>	<i>JN</i>	<i>Freq</i>	<i>Sync</i>	<i>Site name</i>	<i>Ctry</i>	<i>Geocoords</i>	<i>Pr</i>	<i>Bdw</i>	<i>Power</i>	<i>Emrp</i>	<i>Azm</i>	<i>Ant</i>	<i>Hgt</i>	<i>Cond</i>	<i>Rmks</i>	<i>Coord_A</i>	<i>Coord_B</i>
PLN	105100213	HJ	738		MOSKVA	RUS	037E23 55N52	9	16	5	9.9	A		55	3			
PLN	105100213	HN	738		MOSKVA	RUS	037E23 55N52	9	16	5	9.9	A		55	3			
MOD	119124195	HJ	738		NOGINSK MSK	RUS	038E20 55N50	9	16	50	19.8	A		217	3	A/181		
MOD	119124195	HN	738		NOGINSK MSK	RUS	038E20 55N50	9	16	50	19.8	A		217	3	A/181		
PLN	075005356	HJ	1197	S	ASAHIKAWA	J	142E27 43N46	9	15	3	6.9	A		123	1			
PLN	075005356	HN	1197	S	ASAHIKAWA	J	142E27 43N46	9	15	3	6.9	A		123	1			
MOD	120090187	HJ	1197		ASAHIKAWA	J	142E29 43N47	9	15	3	6.8	A		118	3	A/184		
MOD	120090187	HN	1197		ASAHIKAWA	J	142E29 43N47	9	15	3	6.8	A		118	3	A/184		

# Annex to notifying administration

# I

<i>Modification to the Plan</i>				<i>Affected assignment in the Plan</i>				<i>Worst affected point</i>		
<i>Freq</i>	<i>Ctry</i>	<i>Site name</i>	<i>Id No</i>	<i>HJ/HN</i>	<i>Ctry</i>	<i>Freq</i>	<i>Site name</i>	<i>Id No</i>	<i>Azm</i>	<i>Eu_Inc</i>
828	I	Corso Alberto Rivetti-BIELLA	120238912	HN	D	828	FREIBURG	075002533	200	0.62
927	I	PERUGIA	120233671	HN	ALB	927	LIBRAZHD	075003243	260	2.13
	I	PERUGIA	120233671	HN	ALG	927	TIMIMOUN	075003244	40	1.26
	I	PERUGIA	120233671	HN	BEL	927	BRUXELLES WAVR	075003252	240	6.35
	I	PERUGIA	120233671	HN	GRC	927	ZAKYNTHOS	075003269	220	1.53
	I	PERUGIA	120233671	HJ	SVN	918	LJUBLJANA	075003241	180	1.24
	I	PERUGIA	120233671	HN	SVN	918	LJUBLJANA	075003241	180	0.54
	I	PERUGIA	120233671	HN	TUR	927	CANAKKALE	075003299	40	0.91
	I	PERUGIA	120233671	HN	TUR	927	IZMIR	075003300	320	0.62

# Annex to notifying administration

# INS

<i>Modification to the Plan</i>					<i>Affected assignment in the Plan</i>				<i>Worst affected point</i>	
<i>Freq</i>	<i>Ctry</i>	<i>Site name</i>	<i>Id No</i>	<i>HJ/HN</i>	<i>Ctry</i>	<i>Freq</i>	<i>Site name</i>	<i>Id No</i>	<i>Azm</i>	<i>Eu_Inc</i>
792	INS	Jakarta-1	120234562	HN	SNG	792	SINGAPORE 1	075002332	160	1.20
846	INS	Surabaya-2	120234566	HN	AUS	846	CARNARVON WA	075002629	340	2.07
	INS	Surakarta-1	120234567	HN	AUS	846	CARNARVON WA	075002629	340	0.97
1026	INS	Kediri-1	120234576	HN	AUS	1026	PT HEDLAND WA	075004031	60	3.19
1188	INS	Surabaya-7	120234587	HN	AUS	1188	EXMOUTH WA	075005261	220	5.30
1260	INS	Pasuruan-1	120234590	HN	AUS	1260	KARRATHA WA	075005827	300	4.32



# Annex to affected administration

# ALB

<i>Modification to the Plan</i>				<i>Affected assignment in the Plan</i>				<i>Worst affected point</i>		
<i>Freq</i>	<i>Ctry</i>	<i>Site name</i>	<i>Id No</i>	<i>HJ/HN</i>	<i>Ctry</i>	<i>Freq</i>	<i>Site name</i>	<i>Id No</i>	<i>Azm</i>	<i>Eu_Inc</i>
927	I	PERUGIA	120233671	HN	ALB	927	LIBRAZHD	075003243	260	2.13

## Annex to affected administration

## ALG

<i>Modification to the Plan</i>				<i>Affected assignment in the Plan</i>				<i>Worst affected point</i>		
<i>Freq</i>	<i>Ctry</i>	<i>Site name</i>	<i>Id No</i>	<i>HJ/HN</i>	<i>Ctry</i>	<i>Freq</i>	<i>Site name</i>	<i>Id No</i>	<i>Azm</i>	<i>Eu_Inc</i>
927	I	PERUGIA	120233671	HN	ALG	927	TIMIMOUN	075003244	40	1.26

# Annex to affected administration

# AUS

<i>Modification to the Plan</i>					<i>Affected assignment in the Plan</i>				<i>Worst affected point</i>	
<i>Freq</i>	<i>Ctry</i>	<i>Site name</i>	<i>Id No</i>	<i>HJ/HN</i>	<i>Ctry</i>	<i>Freq</i>	<i>Site name</i>	<i>Id No</i>	<i>Azm</i>	<i>Eu_Inc</i>
846	INS	Surabaya-2	120234566	HN	AUS	846	CARNARVON WA	075002629	340	2.07
	INS	Surakarta-1	120234567	HN	AUS	846	CARNARVON WA	075002629	340	0.97
1026	INS	Kediri-1	120234576	HN	AUS	1026	PT HEDLAND WA	075004031	60	3.19
1188	INS	Surabaya-7	120234587	HN	AUS	1188	EXMOUTH WA	075005261	220	5.30
1260	INS	Pasuruan-1	120234590	HN	AUS	1260	KARRATHA WA	075005827	300	4.32

# Annex to affected administration

# BEL

<i>Modification to the Plan</i>				<i>Affected assignment in the Plan</i>				<i>Worst affected point</i>		
<i>Freq</i>	<i>Ctry</i>	<i>Site name</i>	<i>Id No</i>	<i>HJ/HN</i>	<i>Ctry</i>	<i>Freq</i>	<i>Site name</i>	<i>Id No</i>	<i>Azm</i>	<i>Eu_Inc</i>
927	I	PERUGIA	120233671	HN	BEL	927	BRUXELLES WAVR	075003252	240	6.35

# Annex to affected administration

# D

<i>Modification to the Plan</i>				<i>Affected assignment in the Plan</i>				<i>Worst affected point</i>		
<i>Freq</i>	<i>Ctry</i>	<i>Site name</i>	<i>Id No</i>	<i>HJ/HN</i>	<i>Ctry</i>	<i>Freq</i>	<i>Site name</i>	<i>Id No</i>	<i>Azm</i>	<i>Eu_Inc</i>
828	I	Corso Alberto Rivetti-BIELLA	120238912	HN	D	828	FREIBURG	075002533	200	0.62

# Annex to affected administration

# GRC

<i>Modification to the Plan</i>				<i>Affected assignment in the Plan</i>				<i>Worst affected point</i>		
<i>Freq</i>	<i>Ctry</i>	<i>Site name</i>	<i>Id No</i>	<i>HJ/HN</i>	<i>Ctry</i>	<i>Freq</i>	<i>Site name</i>	<i>Id No</i>	<i>Azm</i>	<i>Eu_Inc</i>
927	I	PERUGIA	120233671	HN	GRC	927	ZAKYNTHOS	075003269	220	1.53

# Annex to affected administration

# SNG

<i>Modification to the Plan</i>				<i>Affected assignment in the Plan</i>				<i>Worst affected point</i>		
<i>Freq</i>	<i>Ctry</i>	<i>Site name</i>	<i>Id No</i>	<i>HJ/HN</i>	<i>Ctry</i>	<i>Freq</i>	<i>Site name</i>	<i>Id No</i>	<i>Azm</i>	<i>Eu_Inc</i>
792	INS	Jakarta-1	120234562	HN	SNG	792	SINGAPORE 1	075002332	160	1.20

# Annex to affected administration

# SVN

<i>Modification to the Plan</i>				<i>Affected assignment in the Plan</i>					<i>Worst affected point</i>	
<i>Freq</i>	<i>Ctry</i>	<i>Site name</i>	<i>Id No</i>	<i>HJ/HN</i>	<i>Ctry</i>	<i>Freq</i>	<i>Site name</i>	<i>Id No</i>	<i>Azm</i>	<i>Eu_Inc</i>
927	I	PERUGIA	120233671	HJ	SVN	918	LJUBLJANA	075003241	180	1.24
	I	PERUGIA	120233671	HN	SVN	918	LJUBLJANA	075003241	180	0.54



# Annex to affected administration

# TUR

<i>Modification to the Plan</i>				<i>Affected assignment in the Plan</i>				<i>Worst affected point</i>		
<i>Freq</i>	<i>Ctry</i>	<i>Site name</i>	<i>Id No</i>	<i>HJ/HN</i>	<i>Ctry</i>	<i>Freq</i>	<i>Site name</i>	<i>Id No</i>	<i>Azm</i>	<i>Eu_Inc</i>
927	I	PERUGIA	120233671	HN	TUR	927	CANAKKALE	075003299	40	0.91
	I	PERUGIA	120233671	HN	TUR	927	IZMIR	075003300	320	0.62